



4105 Browns Bridge Road  
Gainesville, Georgia 30504

# Invoice-GA

Date	Invoice No.
5/19/2023	86506

Bill To
Mrs. Chris Goepner 621 S. Lakeview Drive Lowell, Indiana 46356

Lake Address
Mrs. Chris Goepner 621 S. Lakeview Drive Lowell, IN 46356

Rep	Zone	Permit No.	Terms	Date Completed	Phone Number	Lake
TC			Upon Receipt	5/19/2023	708-351-0610	Dale
Qty	Item	Description	Site	Class	Price Each	Amount
1	BBHH	Wave Armor Dock: (2) 301779 - 10" Aluminum Cleat (3) 301592 - 60"x120" bridge dock section (1) 300067 - H Beam Connector 50" (3) 301262 - Heritage Post Cover (6) 300978 - Medium Vertical Bumper (3) 301126 - Solar Dock Lights (3) 301574 - Snap in Plugs (3) 301526 - 2" Raised Post Bracket (2) 302414 - Pro Series Filler Cap (set of 4)		Commerc...	10,599.71	10,599.71
	Discount 1P	Discount:		Commerc...	-3,180.71	-3,180.71
		SUBTOTAL				7,419.00
1	ShoreMaster	Shoremaster 1003623 Canopy Leg 1006061 Canopy 25x120 1025277 Canopy Cover		Commerc...	4,144.50	4,144.50
	Discount 1P	Discount:		Commerc...	-1,213.35	-1,213.35
		SUBTOTAL				2,931.15
2	PP240T16	21ft - 2" S40 Galv Pipe	GA	Commerc...	271.82	543.64
	Discount 1P	Discount:		Commerc...	-255.94	-255.94
		SUBTOTAL				287.70
1	Freight COGS	Freight COGS		Commerc...	398.80	398.80
		SUBTOTAL				398.80

I hereby authorize Marine Specialties, Inc. (MSI) to work on my boat dock and/or boat lift and/or shoreline. All materials remain the property of MSI until the sales balance is paid in full. The balance is due upon completion. Boat lift / boat dock repair hourly rate is billed at \$175.00 per hour. All dock repair work has a 30-day guarantee. 3% Processing fee is added to all credit card payments, excluding deposits under \$500.00. 1.5% Finance charge per month will be added to all invoices over 30 days. The purchaser may forfeit the deposit if the job is canceled without suitable causes. MSI is not responsible for any damages to my boat, dock, or property. MSI is not responsible for delays due to acts of God (rain, flood, snow, tornado, etc.). It is the customer's responsibility to ensure the boat plug is securely in place prior to any work being performed by MSI.

<b>SALES TAX (7.0%)</b>	\$0.00
<b>TOTAL</b>	\$11,036.65
<b>PAYMENTS</b>	\$0.00
<b>BALANCE DUE</b>	\$11,036.65